
PLAY AREA SAFETY INSPECTION REPORT

CORFE CASTLE PARISH COUNCIL

Park Name: West St. Play Area.
Location: West St. Corfe Castle BH20 5HQ

///bride.conducted.pounding

Inspection undertaken March 2024
This report issued 16th April 2024

This report is an independent safety assessment and condition report of the playground and its equipment produced by;

Ken Hussey Independent Play Consultant
MIIRSM Grad IOSH Dip NCRQ

REPORT NOTES

The British Standard for Play Equipment Manufacture, Installation & Maintenance is UKEN 1176:2008/2017/19 in parts. It supersedes 1176:1998 which was withdrawn on 31 May 2009. The standard for Safety Surfacing is BSEN 1177. Operators and providers are advised that equipment conforming to EN 1176 requires regular maintenance. Guidance on this and appropriate inspection, maintenance and operation schedules are contained within BS EN 1176-7:2008.

National standards have been published by BSI on children's playground equipment since BS 3178 was first issued in 1959, this standard concentrated on specifications for specific types of equipment. It was replaced in 1979 by BS 5696 which switched focus to a design and safety approach. Playground equipment not complying with the various standards and revisions should not automatically be considered as being unsafe or to require replacement.

Goalposts are examined in this report in accordance with the revised guidelines published in BSEN16579:2018 or BS EN 748. Goalposts not complying with this revision should not automatically be considered as being unsafe or to require replacement.

MUGA's are examined in this report in accordance with guidelines published in BSEN15312:2007 + A1:2010 (Free access multi-sports equipment). Games areas not complying with this guidance should not automatically be considered as being unsafe or to require replacement.

Compliance with a British Standard cannot confer immunity from legal obligations and operators of play areas are required to ensure that their provision meets the statutory legal requirements of The Health & Safety at Work, etc. Act 1974.2. (HSWA), The Management of Health & Safety at Work Regulations 1999 (MHSW) and The Occupiers Liability Act 1957.

In accordance with the above regulations a risk assessment is used to determine what controls may be necessary or identify those in that are in place. This report will recommend actions where appropriate and includes a record of the risk assessments. Any actions identified will be assumed to be the responsibility of the site operator unless otherwise identified. (See Appendix 1-Risk Table).

The inspection and the subsequent report will examine, but are not limited to:

- The general environment surrounding the play area/equipment and the approach(es) to the equipment, detailing any issues that may affect the operators' duty of care under HSWA/MHSW/OLA.
- The condition and nature of the safety surfacing (if any) and its compliance with BSEN 1177 detailing any issues that require the operators' attention also detailing any issues that may affect the operators' duty of care under HSWA/MHSW/OLA
- The condition of the equipment and its compliance with the standards and guidelines shown above detailing any issues that require the operators' attention also detailing any issues that may affect the operators' duty of care under HSWA/MHSW/OLA
- The installation of the play equipment and its compliance with the standards and guidelines above also detailing any issues that may affect the operators' duty of care under HSWA/MHSW/OLA
- An inspection of previous reports (where available) and any actions taken as a result of those reports or that remain outstanding at the date of this inspection.
- The general compliance of the equipment with the standards and guidelines above including verification of manufacturers certification where provided.
- If required, and where possible, it may be necessary to dismantle elements. Sealed units will not be opened but will be subjected to detailed scrutiny.

Time constraints indicated on this report are from the date of issue of the report. Any items considered to be of immediate need of rectification will have been notified in advance of publication.

Table of Contents

REPORT NOTES.....	2
1 OVERVIEW.....	5
Location Picture.....	6
2 ANCILLARIES & EQUIPMENT RISK FINDINGS.....	7
3 DETAILED RECOMMENDATIONS.....	9
4 SPECIFIC FINDINGS.....	10
4.1 Twin Tower with Slide.....	11
4.2 See-Saw.....	12
4.3 Wicksteed 2 Bay Swing Set	13
4.4 Round Trampoline – RADO 125.....	14
4.5 SMP Multi-play unit.....	15
4.6 Wicksteed Rotaplay.....	16
4.7 Single Bay Toddler swing set.....	17
4.8 Fahr Baa (Sheep) Springer	18
4.9 MUGA Goal End.....	19
4.10 Fencing & Gates.....	20
4.11 Goal.....	21
4.12 Signage.....	22
4.13 Seating	23
4.14 Ancillaries	24
5. COSTS	25
APPENDIX 1. RISK TABLE.....	26

1 OVERVIEW

This a small, but reasonably popular, playground next to a busy footpath on the route to school and so gets used in the mornings. The play site is overlooked by nearby housing and access is via a car park in a cul-de-sac and the adjacent field. The nearest roads are not adjacent to the play area. .

The surfacing is Bonded Rubber Mulch, rubber tiles, and grass mats on the newly installed equipment and as such is suitable for the equipment installed and satisfies BSEN 1177 standard and requires no additional testing.

The Play Area occupies an area of approximately 750m² (50m x 15m)

The adjoining recreation area is approximately 4500m² (78m X 58m)

The overall risk for at the time of the inspection was Low.

Location Picture



2 ANCILLARIES & EQUIPMENT RISK FINDINGS

Ancillaries					
No.	Item	Condition	Risk/Risk Level	Control / Control required	By When
1	Fencing	Requires attention	6 /Low	Keep suitably maintained / Repair damaged sections near car park	Ongoing / 6 months
2	Signage	Satisfactory	2 /Low	Keep suitably maintained	Ongoing
3	Gates	Satisfactory	2 /Low	Keep suitably maintained	Ongoing
4	Bin	Satisfactory	2 /Low	Keep suitably maintained	Ongoing
5	Benches	Satisfactory	3 /Low	Keep suitably maintained	Ongoing
6	Picnic Table	Satisfactory	2 /Low	Keep suitably maintained	Ongoing
7	Safety Surface	Satisfactory	4 /Low	Keep suitably maintained	Ongoing
Overall Risk For Ancillary Items at time of inspection				Low	3

Play Equipment					
No.	Item	Condition	Risk/Risk Level	Control / Control required	By When
8	AF Play Tower	Satisfactory	6 /Low	Keep suitably maintained /Monitor	Ongoing
9	See-Saw	Requires attention	5 /Low	Correct installation errors	Within 3 months
10	Two bay Swing Set	Satisfactory	4 /Low	Keep suitably maintained	Ongoing
11	Trampoline	Satisfactory	2 /Low	Keep suitably maintained	Ongoing
12	Multi Play	Satisfactory	4 /Low	Keep suitably maintained	Ongoing
13	Rotaplay	Satisfactory	3 /Low	Keep suitably maintained	Ongoing
14	Toddler Swing	Satisfactory	3 /Low	Keep suitably maintained	Ongoing
15	Springer	Satisfactory	4 /Low	Keep suitably maintained	Ongoing
16	MUGA End	Satisfactory	2 /Low	Keep suitably maintained	Ongoing
17	Goal	Satisfactory	2 /Low	Keep suitably maintained	Ongoing
Overall Risk for Equipment at time of inspection				Low	4

Environment					
No.	Item	Status	Risk/Risk Level	Control / Control required	By When
18	Access to traffic	Exit to footpath are some distance to the nearest road.	4 /Low	Maintain gates	Ongoing
19	Layout	Satisfactory	2 /Low	Keep suitably maintained	Ongoing
20	Overlooked	The site is overlooked	2 /Low	There is good visibility of the site	N/A
21	General Approach	Satisfactory	2 /Low	The approaches are clear and should be kept clear of obstructions.	Ongoing
Overall Risk for Environmental factors at time of inspection				Low	3

3 DETAILED RECOMMENDATIONS

Item	Issue	Recommendation
4.1	Fall from height	Monitor use for any reported falls
4.9	Powder coating failing	Re-powder coat panels
4.10	Damaged area by car park	Repair /Tidy up broken sections
4.13	Untreated timber	Treat timbers
4.13	Unsupported tables	Provide bases

4 SPECIFIC FINDINGS

Several new items have been installed to replace the older failing units. One (the see saw) requires some minor remedial action and this was notified on the day of the inspection.

There is an area of disrepair in the fencing near the small car park. The gate at this location is now loose in the ground. This area requires attention as the failing timbers will expose fixings such as nails as they further decay which could pose a risk of more significant injury.

Powder coating on the MUGA end is failing.

The surfacing on the two-bay swing is in a poor state of repair.

The picnic tables are twisting and causing additional load on the fixings as well as deforming the plastic. The fixings on these benches will pull free of the plastic if the frame is placed under strain. Investing in more durable recycled plastic benches is a sensible use of Parishioners' funds but only if the units are properly installed and maintained.

Timbers should be regularly treated to prevent decay.

4.1 Twin Tower with Slide

Item No. Bespoke Andy Frost Design

Manufactured: Sovereign Play 2015

CFH:1.7m

Safety Surface:

There are no significant issues with this unit.

The unit is designed to have challenging elements and as such the higher-level components are not easily accessible. As with any such unit there is a higher risk level associated with its use, but this is within acceptable limits and suitable controls are present.



4.2 See-Saw


Item No. K-65-4

Manufactured: Caledonian

CFH: 0.7

Safety Surface: Grass / Grassmat

This newly installed item is in reasonable condition. Some post installation corrective action is required and this was notified on the day of inspection. An area of ground had not been sufficiently compacted and a hole had formed below the bump pad. One bump pad had been overtightened without the use of a washer and the screw head had punched through.



4.3 Wicksteed 2 Bay Swing Set

Item No. 6040-104

Manufactured: Wicksteed 2021/22

CFH: 1.45m

Safety Surface: EPDM Wetpour

There are no significant issues with this unit other than the surfacing, which is in average condition.



4.4 Round Trampoline – RADO 125

Item No. MA-SA-01

Manufactured: Inter-Play

CFH: 0.4m

Safety Surface: Grass / Grassmat

This newly installed item is in excellent condition.



4.5 SMP Multi-play unit

Item No. N/K

Manufactured: SMP

CFH: 1.5m

Safety Surface: Grass / Grassmat

There are no significant issues with this unit.



4.6 Wicksteed Rotaplay

Item No. 6020-020

Manufactured: Wicksteed

CFH: 0.1m

Safety Surface: Rubber tile

There are several minor issues with this unit (see Q2 Report) which remain unchanged.

Otherwise this unit is in reasonable condition.



4.7 *Single Bay Toddler swing set*

Item No. K13-D-MIDI

Manufactured: Caledonian Play

CFH: 1.2m

Safety Surface: Grass mats / grass

This newly installed item is in excellent condition.



4.8 *Fahr Baa (Sheep) Springer*


Item No. FS2007

Manufactured: Fahr Industries

CFH: 0.6m

Safety Surface: Grass mats / grass

This item is in reasonable condition.



4.9 MUGA Goal End

Item No. n/k

Manufactured: n/k

CFH: n/a

Safety Surface: Grass mats / grass


There are no issues with this unit other than the condition of the powder coating previously reported.



4.10 Fencing & Gates

There are no significant issues with the gates or most of the fencing other than the kissing gate from the car park area which is now decaying and is loose in the ground.

There is a section of fencing in a state of disrepair next to the parking area which continues to pose a minor hazard.



4.11 Goal

This unit is in average condition.



4.12 Signage

There is clear sign displaying operator & emergency contact details and location information and this is displayed in several locations.

There is an appropriate sign displayed on the MUGA goal end.



4.13 Seating

One recycled bench has been moved into the shelter (whether by user or by design is unknown) and the effect of the previous distortion can be clearly seen in the picture (right).

Consideration should be given to setting the tables on bases and fixing them in position.



4.14 Ancilliaries

There is stone built shelter with cast seating. There are no obvious issues with this structure.

There is a refuse bin adjacent to the shelter and there are no obvious issues with the bin.



5. COSTS

Item	Issues	Recommendation (s)	Supply Only	Supply & fit
------	--------	--------------------	-------------	--------------

APPENDIX 1. RISK TABLE

Severity	
1	Minor
2	Moderate
3	Serious
4	Major
5	Life Changing

Probability	
1	Highly Unlikely
2	Low Likelihood
3	Possible
4	Likely
5	Highly Likely

		Probability				
		1	2	3	4	5
Severity	1	1	2	3	4	5
	2	2	4	6	8	10
	3	3	6	9	12	15
	4	4	8	12	16	20
	5	5	10	15	20	25

RISK SCORING		
1-6	Low Risk	There is a very low likelihood of any injury. At the upper end of the scale there may be more risk to very young or vulnerable users
8-16	Medium Risk	There is an increased possibility of injury and control measures may be required to reduce the likelihood or severity of injury. At the upper end of the scale there may be a need for increased control measures or access restrictions and monitoring and maintenance requirements may be more frequent
20-25	High Risk	The likelihood of significant injury is close to certain and use of the equipment or play area should be curtailed immediately. Measures must be in place to prevent further use until corrective action has been completed