

Playground Monthly Inspection Report

Date inspection carried out: 16/01/2022

Name of person carrying out inspection: T.LEE

1 Bay 2 Seat (Cradle)

Swing 1 – Left swing as facing the front of the unit.

Swing 2 – Right swing as facing front of the unit.

	Sound	Small Defect	Large Defect	Comments
Movement of swing 1	Y			
Movement of swing 2	Y			
Chains Swing 1	Y			
Chains Swing 2	Y			
Seat Swing 1	Y			
Seat Swing 2	Y			
Frame	Y			

Roundabout

	Sound	Small Defect	Large Defect	Comments
Movement				N/A
Seats				N/A
Rails				N/A
Safety Ground				N/A

Multi Play (Junior)

	Sound	Small Defect	Large Defect	Comments
Slide	Y			
Frame	Y			
Safety Ground	Y			

Rocking Horse

	Sound	Small Defect	Large Defect	Comments
Movement	Y			
Seats	Y			
Rails	Y			
Safety Ground	Y			

Spring Sheep

	Sound	Small Defect	Large Defect	Comments
Movement	Y			
Seats	Y			
Rails	Y			
Safety Ground	Y			

2 Bay 4 Seat (Flat)

Swing 1 – Far Left swing as facing the front of the unit.

Swing 2 – Middle left swing as facing front of the unit.

Swing 3 – Middle right swing as facing front of the unit.

Swing 4 – Far right swing as facing front of the unit.

	Sound	Small Defect	Large Defect	Comments
Movement of swing 1	Y			
Movement of swing 2	Y			
Movement of Swing 3				Not in situ. Being replaced with basket swing
Movement of Swing 4				Not in situ. Being replaced with basket swing
Chains Swing 1	Y			
Chains Swing 2	Y			
Chains Swing 3				N/A
Chains Swing 4				N/A
Seat Swing 1	Y			
Seat Swing 2	Y			
Seat Swing 3				N/A
Seat Swing 4				N/A
Frame		Y		RUST ON THE CROSS BEAM
Safety Ground		Y		MATS UNDER SWINGS SHRUNK AND CURLING

See Saw

	Sound	Small Defect	Large Defect	Comments
Movement	Y			
Seats	Y			
Rails	Y			
Safety Ground	Y			

General Site

A large, empty rectangular box with a thin black border, intended for site details or a drawing.

Sign T. LEE

Date 16/01/22