

Playground Monthly Inspection Report

Date inspection carried out: 13/08/22

Name of person carrying out inspection: TIMOTHY LEE

1 Bay 2 Seat (Cradle)

Swing 1 - Left swing as facing the front of the unit.

Swing 2 – Right swing as facing front of the unit.

	Sound	Defect	Comments
Movement of swing 1	Y		
Movement of swing 2	Y		
Chains Swing 1	Y		
Chains Swing 2	Y		
Seat Swing 1	Y		
Seat Swing 2	Y		
Frame	Y		

Roundabout

	Sound	Defect	Comments
Movement	Y		
Seats / Rails	Y		
Safety Ground	Y		

Multi Play (Junior)

	Sound	Defect	Comments
Slide	Y		
Frame	Y		
Safety Ground	Y		

Rocking Horse

	Sound	Defect	Comments
Movement	Y		
Seats	Y		
Rails	Y		
Safety Ground	Y		

Spring Sheep

	Sound	Defect	Comments
Movement	Y		
Seat	Y		
Rail	Y		
Safety Ground	Y		

See Saw

	Sound	Defect	Comments
Movement	Y		
Seats	Y		
Rails	Y		
Safety Ground	Y		

2 Bay 2 x Flat Seats & 1 Basket

Swing 1 – Far Left swing when facing the front of the unit.

Swing 2 – Swing in between

Swing 3 – Basket Swing

	Sound	Defect	Comments
Movement of swing 1	Y		
Movement of swing 2	Y		
Movement of Basket Swing	Y		
Chains Swing 1	Y		
Chains Swing 2	Y		
Chains Basket	Y		
Seat Swing 1	Y		
Seat Swing 2	Y		
Seat Basket	Y		
Frame		Y	WORN PAINTWORK AND RUST
Safety Ground		Y	MATting LIFTED, TRIP HAZARD

Out of the Ruins – Hollow Tree (Northwest Corner)

	Sound	Defect	Comments
Platform	Y		
Structure	Y		

Out of the Ruins – Burma Bridge / Balance Beam

	Sound	Defect	Comments
Walking Platform	Y		
Structure	Y		

Out of the Ruins – Tower (Northeast Corner)

	Sound	Defect	Comments
Ramp	Y		
Fireman's Pole	Y		
Ladder	Y		
Climbing Vines	Y		
General Structure	Y		
Platform	Y		

Out of the Ruins – Horizontal Net

	Sound	Defect	Comments
General Structure	Y		

Out of the Ruins – Nest Platform

	Sound	Defect	Comments
Ladder	Y		
Climbing Pole	Y		
Platform	Y		
Rails / Frame	Y		
General Structure	Y		

Out of the Ruins – Battlement Bridge

	Sound	Defect	Comments
Platform	Y		
Rails	Y		
General Structure	Y		

Out of the Ruins – Ruined Tower & Trapeze Rings

	Sound	Defect	Comments
Rings	Y		
Platform	Y		
Ruin Steps	Y		
Climbing Rope	Y		
General Structure	Y		

Out of the Ruins – Traverse Course & Climbing Wall

	Sound	Defect	Comments
Walking Platform Traverse Course	Y		
Climbing grips	Y		
General Structure	Y		

Out of the Ruins - General

	Sound	Defect	Comments
Safety Flooring	Y		

Fence / Gates

	Sound	Defect	Comments
Wooden Posts / Panels North & West	Y		
Chain link Posts / Wires South & East		Y	LOOSE POSTS & WIRES PROTRUDING
Movement East Gate	Y		
Movement Vehicular Gate	Y		
Movement West Gate	Y		
Ground East gate	Y		
Ground Vehicular Gate	Y		
Ground West Gate	Y		
Frame East gate	Y		
Frame Vehicular Gate	Y		
Frame West Gate		Y	Gate post split

Basketball Court Area

	Sound	Defect	Comments
Structure		Y	BOLT COVERS MISSING
Hoop	Y		
Goal area ground	Y		

General Site

--

Sign

Tim Lee – Parish Caretaker

Date

13/08/22